

830 Douglas Ave.
Dunedin, FL 34698
(727)733-2447
Fax:(727)733-3962
www.OceanOptics.com



—A—
HALMA
GROUP
COMPANY

JAZ-INDY Addendum

To Our Valued JAZ-INDY Customers:

Issues for the first release of the JAZ-INDY include the following:

- It is recommended that unused Serial ports be disabled to reduce power consumption.
- When sending a request over the Serial port, wait for a response before sending another request to avoid a lock-up condition.
- When flow control is enabled, it may be necessary to send a character other than <control-s> to resume the flow of characters. This issue applies to both types of flow control.

Please contact us for any issues or concerns. Our contact information is located on the front cover of your [Jaz Installation and Operation Manual](#) and on our website at: <http://www.oceanoptics.com/ContactUs.asp>.